



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
NORTHFIELD AVENUE	o/s 41	Damaging	TR: Felling- - Significant lateral rooting at surface - cannot resurface adequately	Prunus x hilleri spire	Plant in new 800mm pit o/s 41, (same as felled tree)	Sorbus 'Schouten'
NORTHFIELD AVENUE	o/s 9	Damaging	TR: Felling- - Significant lateral rooting at surface - cannot resurface adequately	Sorbus aucuparia	Plant in new 800mm pit o/s 9, (same as felled tree)	Sorbus 'Schouten'